

## ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ ਦੋਰਾਹਾ।

₹स,

ਪ੍ਰਿੰਸੀਪਲ, ਸੰਤ ਇਸ਼ਰ ਸਿੰਘ ਜੀ ਮੈਮੋਰੀਅਲ ਪਬਲਿਕ ਸਕੂਲ, ਕਰਮਸਰ ਰਾੜਾ ਸਾਹਿਬ ।

8.40

H31. 26/4/24

ਵਿਸ਼ਾ:

Issue of School Building Safety Certificate .

ਹਵਾਲਾ:

ਆਪ ਦਾ ਪੱਤਰ ਨੰ. 20066 SIS/III/2024/180 ਮਿਤੀ.22.03.2024 ਅਤੇ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ.3 ਲੋ.ਨਿ.ਵਿ. ਭ. ਤੇ ਮ. ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ ਜੀ ਦਾ ਪਿੱਠ ਔਕਣ ਨੰ. 71 ਮਿਤੀ. 09.04.2024

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਆਪ ਵੱਲੋਂ ਦਿੱਤੇ ਗਏ ਦਸਤਾਵੇਜਾਂ ਅਨੁਸਾਰ ਉਕਤ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ Visual ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ ਅਤੇ ਪਾਇਆ ਗਿਆ ਹੈ ਕਿ ਨੱਥੀ ਪ੍ਰੋਫਾਰਮੇ ਦੇ Part-II ਵਿੱਚ ਦਰਸਾਈਆਂ ਸ਼ਰਤਾਂ ਦੇ ਅਧਾਰ ਤੇ ਉਕਤ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਵੇਖਣ ਨੂੰ ਸੁਰੱਖਿਅਤ ਜਾਪਦੀ ਹੈ । ਇਸ ਸਰਟੀਫਿਕੇਟ ਦੀ ਮਿਆਦ ਮਿਤੀ 28.02.2025 ਤੱਕ ਹੈ। ਇਸ ਤੋਂ ਇਲਾਵਾ ਇਹ ਸਰਟੀਫਿਕੇਟ ਆਪ ਨੂੰ ਇਸ ਸ਼ਰਤ ਤੇ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ ਕਿ ਜੇਕਰ ਆਪ ਵੱਲੋਂ ਉਕਤ ਸਰਟੀਫਿਕੇਟ ਲਈ ਜਮ੍ਹਾਂ ਕਰਵਾਈ ਗਈ ਫੀਸ ਵਿੱਚ ਕਿਸੇ ਵੀ ਕਿਸਮ ਦਾ ਵਾਧਾ ਹੁੰਦਾ ਹੈ ਤਾਂ ਆਪ ਉਹ ਜਮ੍ਹਾਂ ਕਰਵਾਉਣ ਦੇ ਪਾਬੰਦ ਹੋਵੇਗੇ। ਜੇਕਰ ਕੋਈ ਕੁਦਰਤੀ ਆਫਤ ਆਉਂਦੀ ਹੈ ਤਾਂ ਤਰੁੰਤ ਇਸ ਦਫਤਰ ਨੂੰ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇਂ।

ਨੱਥੀ/ ਉਪਰੋਕਤ ਅਨੁਸਾਰ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਲੋ.ਨਿ.ਵਿ. (ਭ ਤੇ ਮ) ਸਾਜ਼ਾ, ਦੋਰਾਹਾ।

ਪਿੱਠ ਔਕਣ ਨੰ

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ. 3, ਲੋ.ਨਿ.ਵਿ. (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰ. 71 ਮਿਤੀ 09.04.2024 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜ ਕੇ ਰਿਪੋਰਟ ਕੀਤੀ ਜਾਂਦੀ ਹੈ ਕਿ ਸਕੂਲ ਵੱਲੋਂ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਰਕਮੀ 5,000/- ਰੁਪਏ, E-Challan Receipt No 11033354 Dated 08.04.2024 ਰਾਂਹੀ Head 0059-01-102-01-00 ਅਤੇ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਰਕਮੀ 5,000/- ਰੁਪਏ, E-Challan Receipt No 11230836 Dated 19.04.2024 ਰਾਂਹੀ Head 0059-01-102-01-00 ਵਿੱਚ ਜਮ੍ਹਾਂ ਕਰਵਾਈ ਗਈ ਹੈ। ਕ੍ਰਿਪਾ ਕਰਕੇ ਫੀਸ ਆਪਣੇ ਪੱਧਰ ਤੇ ਵੈਰੀਫਾਈ ਕਰਨ ਦੀ ਕ੍ਰਿਪਾਲਤਾ ਕੀਤੀ ਜਾਵੇ ਜੀ।

> ਸੂਹੀ/ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਲੋ.ਨਿ.ਵਿ. (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ, ਦੋਰਾਹਾ।

PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
to Head of School/ Institutes PART- 1 (To be filled by the Head of School/ Institute

| 1.  | Name of the School   |   |
|-----|--|---|
| 2.  | Location   | : Sant Ishar Singh Jl Memorial Public<br>School                 |
| 3.  | Plot Area  | Karamsar Rara Sabib, Tebsii Payal<br>Distt. Ludhlana            |
| 4.  | Plinth Area  | :<br>81 Bigha – 11 Biswa  |
| 5.  | Number of Storey's   | 4646.84 Sq.M.   |
| 6.  | Year of Construction of Building   | 03  |
| 7.  | If the building has been and   | : 1988  |
| a)  | Of the qualified Engineer, the following details may be given Name of the Engineer with qualification                  | :   |
| b)  | Address of Engineer  | : Er. Amarjeet Singh Jabbal<br>2/44 , Kirti Nagar, W.H. Scheme, |
| c)  | Set of Structural drawings used in the construction, if available  | New Delhi   |
| d)  | Name & address of Architect with qualification   | Er, Amarjeet Singh Jabbal                                       |
| 8.  | Whether the building has been constructed for the purpose  |   |
| a)  | School   | YES/NO  |
| b)  | Residential Purpose and converted for use as a School  | : YES/NO  |
| 9.  | Materials used for roofs   | · Falsia  |
| a)  | R.C.C. Slabs/R.B.C. Slabs  | YES/NO  |
| b)  | R.S. Joist & Battons   | YES/NO  |
| c)  | Wooden joists & Battons  | YES/NO  |
| 10. | Materials used for walls   | YES/NO  |
| a)  | Mud Mortar   | YES/NO  |
| b)  | Cement Mortar  | YES/NO  |
| c)  | Lime Mortar  | /   |
| 11. | Flooring   | YES/NO  |
| a)  | Conglomerate   | YES/NO  |
| b)  | Теггаzо  | YES/NO  |
| c)  | Brick Paving.  |   |
| 12. | Brick Paving.  A detailed drawing indicating dimensions of the rooms  Alongwith size and location of doors and windows |   |
|     | (Attached)   | (   |

Signature with Stamp of the seal Of the School/Institution.

Principal Sant Ishar Singh Ji Memorial Public School Karamsar Rara Sahib

### No!-40

# Date !- 26/4/24

- a) visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- In case any addition/ alteration or expansion and modifications to this buildings is to be carried b) out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability c) and safety of the building.

This building can be safety occupied for normal use upto (indicate upto which it can be used) d)

Sub Divisional Engineer Construction Sub Division 3